



Typical SolderSleeve Device (illustration of shield terminator concept)



Typical Installation

1. Insert prepared cable



2. Apply heat

